

General Environmental Incident Summary

Incident: 1831 **Date/Time Notice:** 12/7/2012 1330 **DEM Incident No:**

Responsible Party: Schlehr Utility Construction LLC

Date Incident: 12/3/2012 **Time Incident:** 1530 **Duration:**

County: Mountrail **Twp:** 157 **Rng:** 92 **Sec:** 18 **Qtr:**

Lat: 48.42334 **Long:** -102.61410 **Method:** Derived from TRS

Location Description: From Powers Lake go east on Hwy 50 til you get to hwy 11 then go south to 74th st. Then go w to 91st which is approx 3 1/2 miles. Then go s to 70th ST then east 1 mile and head back s for 1/2 mile to spill location.

Submitted By: Susan Schlehr

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Jim Schlehr
PO Box 711
Garrison, ND 58540

Distance Nearest Occupied Building:

Type of Incident: salt water spill

Description of Released Contaminant: salt water pipeline

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Was drilling under a road and hit a saltwater pipeline.

Risk Evaluation:

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

Bill Buckley with Oasis was contacted immediately his # 406 480-4453. Also Scott with Strata was brought in for clean up his # 720-8565. For any other information you can contact Jim Schlehr at 340-0973.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/7/2012 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Bore was under county road and both sides of road may have been impacted. Earthmovers made original response. Follow up to ensure adequate cleanup.

Date: 12/10/2012 **Status:** Reviewed - Follow-up Required

Author: Harries, Alison

Updated Volume:

Notes:

A correction to the location was sent only to Alison who corrected it in the database. The incident occurred in Section 18, not 8.

Date: 1/24/2013 **Status:** Inspection

Author: Clary, Shane

Updated Volume:

Notes:

Department personnel reviewed the soil samples that were submitted and are satisfied with the clean-up.

Date: 1/25/2013 **Status:** Inspection

Author: Clary, Shane

Updated Volume:

Notes:

Shane Clary and Adam Miller inspected this pipeline leak. The company contact was contacted about this leak and confirmed that approximately 300 feet along the pipeline was excavated and removed. Strata was brought in for the clean up and contacted about their clean up plans. Strata personnel say they will send their sampling results to the Department to verify proper clean up.